

Fresenius Kabi Canada Ltd.

165 Galaxy Blvd, Suite 100 Toronto, Ontario Canada M9W 0C8 T: 905.770.3711 F: 844.513.1522 W: fresenius-kabi.ca

July 21, 2022

Heparin Sodium Injection, USP 10,000 USP units/mL MD Vial 5 mL Product Changes

Dear Valued Customer,

Fresenius Kabi Canada would like to advise that the following changes have been made to our **Heparin Sodium Injection, USP 10,000 USP units/mL MD Vial 5 mL:**


- Vial: There have been changes to the vial size and cap colour.
- **Labelling:** The tray and vial labels have been updated to include the new Fresenius Kabi Canada brand design and Plain Language Labelling (PLL) requirements.
- **Product code:** The new product code is outlined in the table below.

A more detailed look at the current verses "new" labelling can be found in the table below. There has been no change to the formulation, the stopper remains **latex-free**, and the product is **not free** from **preservatives**.

DIN	Product Description	Current Product Code	NEW Product Code	Current UPC Codes	NEW UPC Codes	NEW MDP Code	NEW McKesson Code	Availability Date
02264307	Heparin Sodium Injection, USP 10,000 USP units/mL MD Vial 5 mL	C504805	C504214	Vial: 629336508051 Tray: 629336000364	Vial: 629336004904 Tray: 629336004911	976325	168720	Aug. 1, 2022

Please note, during this transition period the current product code may still be in distribution until inventory is depleted, at which point the current product code will be **discontinued**.

Labelling & Component Changes:



If you would like to obtain more information on this product, please contact your hospital representative or our Customer Service Department at (877) 821-7724.

Sincerely,

(3)

George Shamsoun Associate Director – Marketing, IV Drugs george.shamsoun@fresenius-kabi.com